TWOTRONIC

XENTRY Vehicle Detector


XENTRY VEHICLE DETECTOR powered by TWOTRONIC
TWOTRONIC
TWOTRONIC
PREPARED FOR
TIRE TREAD READER
OPTIONAL TIRE PROFILE DOCUMENTATION
MOBILE APP FOR ADDING PICTURES
COMPLETE 360° DOCOMENTATION
CUSTOMERS DRIVE THEMSELVES
AI
ARTIFICIAL INTELLIGENCE
OUTDOOR PROOF
5G
5G / LTE OPTION
API
REST-API INTERFACE

Mercedes-Benz



3 m

Mercedes France, Service Summit, 2024

// 12 BUSINESS CASES IN 4 AREAS

TRANSFER OF RISK

No more discussions with customers about damages caused during visits.

Automated condition documentation for test drive and rental cars.

Automated condition documentation for new and used car deliveries.

EFFICIENCY GAINS

Digital service reception enables reduction of process times.

Time expenditure for manual condition checks in service, rent and sales can be reduced.

Time expenditure for manual tire profile measurement and tire documentation can be reduced.

Time expenditure for manual underbody checks can be reduced.

CROSS-SELLING

Tires

Rims / Rim-Repair

Body Damages / Spot repair

REPORTS APPRAISALS

Residual Value Reports Leasing Return

Insurance Reports

Dashboard
Scanübersicht
Scanübersicht LIVE
Statistiken
Protokoll

Sprache ändern
Administration
Ausloggen
Informationen

Api Version: v1 (1.3.6.838)
Frontend Version: 1.3.4.0542

Suche Scans...

MEHR FILTER

Hauptbild	Kennzeichen	Kennzeichenbild	Scanzeitpunkt	Reifen	Schäden	Berichte	Aktionen
			26.03.2024 08:12:11		0 0	0	
			26.03.2024 08:11:27		0 0	0	
			26.03.2024 08:08:44		2 0	0	
			26.03.2024 08:07:08		0 0	0	
			26.03.2024 08:06:49		0 0	0	
			26.03.2024 08:05:38		0 0	0	

Elemente pro Seite: 30 Elemente 271-300 von 8596 (Seite: 10 /287)

With the TwoTronic app, employees can receive customized **PUSH NOTIFICATIONS**

The app allows scans to be supplemented with **ADDITIONAL INFORMATION** (examples: interior images or pictures of vehicle documents, ...)

CHECKLISTS can also be edited directly in the app

qa.fahrzeugscan.de/Scans/ScanDetailViewer/1167

XENTRY VEHICLE DETECTOR

OVERVIEW | Scan Detail Viewer | Images Overview | Checklisten | Damages Overvie



Customer- and Orderdata

Car Information:

No information available!

Tyre data (all tires):

Season	Winter tires
Brand	PIRELLI
Tire Model	SOTTOZERO3
DOT Code	DOTXBW2V7823421
Production Date	August 2021
Age [years]	3.4
Width	245
Height	45
Rim Diameter	19
Load Capacity Index	102
Speed Index	V

Order Information:

No information available!

Customer Information:

AUTOMATED TIRE IDENTIFICATION

Our new tire camera helps to identify the tire by reading the text from ist side wall.



Kunden- und Fahrzeuginformationen

Fahrzeug-Informationen:
Keine Informationen verfügbar!

Auftragsinfos:
Keine Informationen verfügbar!

Kundeninformation:
Keine Informationen verfügbar!

Schadendetails

Felgenschaden Leicht

Kein Schaden ausgewählt...

Legende: Neu · Bearbeitete · Gelöscht

0 ungespeicherte Änderung(en)

SPEICHERN | VERWERFEN

Beim Verlassen speichern: **Aktiv**

Scanübersicht

Scan nicht überprüft

26.03.2024 08:08:44

GS001_BMW_Muc_FFR-1

GUTACHTEN ANFORDERN



Customer- and Orderdata

Car Information:

No information available!

Tyre data (all tires):

Season	Summer tires
Brand	-
Tire Model	-
DOT Code	-
Production Date	-
Age [years]	-
Width	-
Height	-
Rim Diameter	-
Load Capacity Index	-
Speed Index	-

Order Information:

No information available!

Customer Information:

No information available!

EDIT | DELETE

Proposaldetails

Executed AI scripts: TT_AI

No proposals available...

0 unsaved change(s)

SAVE | DISCARD

Save on leave: **Active**

Scan-Overview

Scan not reviewed

KO230FE

1/22/2025 11:40:56 AM

GS0001_MesseA2-1

VEHICLE REPORT



Datos de clientes y pedidos

Información del coche:
No hay información disponible!

Información del pedido:
No hay información disponible!

Información del cliente:
No hay información disponible!

Detalles de la propuesta

No hay propuestas disponibles...

0 Cambios(s) no guardados.

SALVAR | DESCARTAR

Ahorre en vacaciones: **Activo**

Descripción general del escaneo

Escaneo no revisado

1683 ك ج

27/3/2024 13:34:30

GS00110831-1

SOLICITAR INFORME



Datos de clientes y pedidos

Información del coche:
No hay información disponible!

Información del pedido:
No hay información disponible!

Información del cliente:
No hay información disponible!

Detalles de la propuesta

No hay propuestas disponibles...

0 Cambios(s) no guardados.

SALVAR | DESCARTAR

Ahorre en vacaciones: **Activo**

Descripción general del escaneo

Escaneo no revisado

1683 ج ك

27/3/2024 13:34:30

GS00110831-1

SOLICITAR INFORME

Scan-Galerie

07.05.2024 08:53 [redacted]

Perspektive

Vorne | Rechts | Links | Dach | Unte

Alle auswählen

Bilder in

// AUTOMATED RIM DAMAGE DETECTON



Kunden- und Fahrzeuginformationen

Fahrzeug-Informationen:

Keine Informationen verfügbar!

Auftragsinfos:

Keine Informationen verfügbar!

Kundeninformation:

Keine Informationen verfügbar!



Schadendetails

Felgenschaden Leicht

Kein Schaden ausgewählt...

Legende: Neu Bearbeitete Gelöscht

0 ungespeicherte Änderung(en)

SPEICHERN VERWERFEN

Beim Verlassen speichern: **Aktiv**

Scanübersicht

Scan nicht überprüft

26.03.2024 08:08:44

GS001_BMW_Muc_FFR-1

GUTACHTEN ANFORDERN

// ULTRA CIRSP 4K PICTURES



Datos de clientes y pedidos

Información del coche:
No hay información disponible!

Información del pedido:
No hay información disponible!

Información del cliente:
No hay información disponible!



Detalles de la propuesta

No hay propuestas disponibles...

0 Cambios(s) no guardados.

SALVAR DESCARTAR

Ahorre en vacaciones: **Activo**

Descripción general del escaneo

Escaneo no revisado

1683 ج ك

27/3/2024 13:34:30

GS00110831-1

SOLICITAR INFORME

// DIRECT XENTRY INTEGRATION

// UNDERBODY PICTURES



// AUTOMATED CONDITION REPORTS



Autohaus Widmann GmbH & Co.KG
Fahrzeugbericht

Fecha: **16/1/2025 16:21:57 16/1/2025 16:21:57**

Tyre profile

All values in 32nds | Warning limit < 5 32nds | Replacemented < 3 32nds

Front Left 9 9 9
Front Right 9 9 8
Rear Left 9 8 8
Rear Right 8 8 8

Braking distance

at 31 mph

+4%
17.5 m New Tires
18.1 m Your Tires

Vorne links
Vorne rechts
Hinten Links
Hinten rechts

// AUTOMATED CONDITION REPORTS

Autohaus Widmann GmbH & Co.KG
Fahrzeugbericht

Matrícula: Fecha: **16/1/2025 16:21:57 16/1/2025 16:21:57**

Daños en la llanta

Recuento de daños y perjuicios: 3





// AUTOMATED CONDITION REPORTS

Autohaus Widmann GmbH & Co.KG
Fahrzeugbericht

Matrícula: **AABG11** Fecha: **16/1/2025 16:21:57 16/1/2025 16:21:57**

Paseo *Visión general del vehículo*

Delantero izquierdo

Trasero izquierdo

Delantero derecho

Trasero derecho

// PRODUCTLINES



Light-Underbody and Light-Tire
Out new light-check product family enables us to create a tire-only and an underbody-only product version. Both versions consist of one side wall that houses the license plate camera and the corresponding tire and or underbody modules.



Upgradability: Our light scanners can be upgraded with all other avalable features at any time. We can even exchange light check for quick-check side walls if desired.

Our **Light-Check s**canner will be available from Q4 2023 and is our entry-level model for small car dealerships. He dispenses with everything inessential and can score with a low entry price.



Our **Quick-Check** scanner has been in production for over 10 years and is now in its third product generation - although the models of the first generation are still in use today. The special thing about our Quickcheck product is its patented movable camera column. It brings the customer two decisive advantages: No matter how fast a customer drives through the scanner, the scanner always takes the same number of images from the same angles. When not in use, the camera column rotates to a sheltered position that protects the cameras from environmental elements such as rain, snow and sand.



We developed our **Precision-Check** for customers who focus on damage to the paintwork. The scan results impress with their enormous image quality. Disadvantage: The maximum passage speed is significantly reduced.

SALES

Oscar Tseng
oscar@rhinocapgroup.com
+1 (949) 568 8381